APPENDIX C

Photograph Log and Photographs

PHOTO LOG

The photographs were taken using a PENTAX Optio W80 digital camera during the inspection. Kevin Lilly of the West Virginia Department of Environmental Protection took all photographs. Original copies of the Photos are on a CD in the file. Photo coordinates were recorded using a GPS unit.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 1	2011-06-1609.45.28.JPG		GPS unit showing time of 9:33:24 AM.
Photo 2	2011-06-1609.45.37.JPG		(Integrator)
Photo 3	2011-06-1610.33.29.JPG		Chicken House No. 4, front View
Photo 4	2011-06-1610.34.07.JPG		Chicken House No. 4, East View
Photo 5	2011-06-1610.36.26.JPG		Drainage from Co. Rt. 7, leading to culvert that goes under House No. 4. Drainage is flowing west towards South Fork River.
Photo 6	2011-06-1610.39.03.JPG		Sidewall ventilation, east side of House No. 4
Photo 7	2011-06-1610.40.04.JPG		Hose to flush drinking water system. House No. 4, east side.
Photo 8	2011-06-1610.41.04.JPG		South side entrance of House No. 4.
Photo 9	2011-06-1610.42.34.JPG		Culvert influent
Photo 10	2011-06-1610.43.08.JPG		Ditch line on east side of House No. 4, discharges through this culvert at farm access road, west of House No. 4.
Photo 11	2011-06-1610.45.36.JPG		Discharge from culvert that flows under House No. 4 (see Photo 5). Flows into pond.
Photo 12	2011-06-1610.46.49.JPG		Overall view of pond located west of No. 4 and south of No. 3.
Photo 13	2011-06-1610.47.36.JPG		Runoff ditch to pond between No. 4 and No. 3.
Photo 14	2011-06-1610.48.11.JPG		Access road between No. 4 and No. 3. Drains to pond.
Photo 15	2011-06-1610.49.17.JPG		South side entrance to House No. 3.
Photo 16	2011-06-1610.50.17.JPG		Drainage between House No. 3 and No. 2.
Photo 17	2011-06-1610.50.47.JPG		Outlet via culvert from drainage between House No. 3 and No. 2.
Photo 18	2011-06-1610.51.56.JPG		Compost shed located southeast of House No. 2.
Photo 19	2011-06-1610.52.25.JPG		Overall view of compost shed looking south.

¹ Filename based on date and time photo was taken where time is expressed based on the 24 hour clock. Format is YYYY-MM-DD--HH-MM-SS.JPG.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 20	2011-06-1610.53.23.JPG		Dry manure storage shed facing west.
Photo 21	2011-06-1610.54.10.ЈРС		Drainage slanted south in front of dry manure storage shed.
Photo 22	2011-06-1610.55.32.ЈРС		South entrance of House No. 2.
Photo 23	2011-06-1610.56.32.ЈРС		Drainage area between House No. 2 and House No. 1 facing north.
Photo 24	2011-06-1610.57.35.JPG		South side of House No. 1.
Photo 25	2011-06-1610.59.59.JPG		Drainage of north side of dry manure storage shed (See photo 19).
Photo 26	2011-06-1611.02.49.JPG		Drainage on west side of House No. 1.
Photo 27	2011-06-1611.12.30.JPG		Discharge leading north from House No. 1.
Photo 28	2011-06-1611.13.04.JPG		North entrance of House No. 1.
Photo 29	2011-06-1611.14.03.JPG		Drainage off property from House No. 1.
Photo 30	2011-06-1611.16.30.JPG		North entrance of House No. 2.
Photo 31	2011-06-1611.19.51.JPG		Above view of discharge from pond.
Photo 32	2011-06-1611.22.12.JPG		View of point source discharge, facing east of pond
Photo 33	2011-06-1611.25.16.JPG		Discharge point from channel below pond into South Fork.
Photo 34	2011-06-1611.28.26.JPG		Upstream view of South Fork River from bridge.
Photo 35	2011-06-1611.28.45.ЈРС		Downstream view of South Fork River from bridge.
Photo 36	2011-06-1611.29.27.JPG		From bridge, view of discharge channel into South Fork River



Photo 2



Photo 4



Photo 1



Photo 3




Photo 6



Photo 8



Photo 5



Photo 7



Photo 9



Photo 11



Photo 10



Photo 12




Photo 14



Photo 16



Photo 15



Photo 17



Photo 19



Photo 18



Photo 20





Photo 22



Photo 24



Photo 23



Photo 25



Photo 27



Photo 26



Photo 28



Photo 30



Photo 32




Photo 31




Photo 34



Photo 36



Photo 35